Final bill
Recorded on:-

work Code No:-002-18-000024

M. A. R. 57 (Rule 116)
Measurement Book

No. B 166645

Work order No:- EE(YNK.D) E-PmT-19/w.o/31/2018-19, Date 20/08/2018

al No. .....

ne of Work Construction of Drain at Kote bheedhi near Venugopala Swamy Temple in ward No-12 From ..... To .....

ne of Contractor or nature of Agency Sri. G. Muniraju No:-54, 4th Cross, 4th main, Kote Street, Yelahanka, Bangalore-560064 Est Cost:-20.00 Lakhs

e of commencement of work .....

e	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
	2	3	4	5	6	7	8
1	KSRB 2-2.1: Earth work excavation for fourdation of buildings & Culverts water Supply, Sanitary line and electrical Conduits & either in pits or in trenches 1.5m and above in width, in ordinary soil not exceeding 1.5m in depth including dressing the bottom and sides of pits and trenches, stacking the excavated soil clear from edges of excavation with lead up to 50mm after breaking of clods Complete as per Specifications						
	Quantity vide, AR per pre-measurement are recorded in this MB and Page No of:-		46680 :-			80.00 m^3	16780.80
						CRS. 209.76	

Scanned by CamScanner

M. A. R. 57 (Rule 116)
Measurement Book

No. B

166656

No. .....
e of Work ..... From..... To.....
e of Contractor of nature of Agency .....
of commencement of work .....

Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
2	3	4	5	6	7	8
C/F Bill Book 21/5/19						
A.E.E. Ramesh House Road:-	4	1.25	-	-	5.00	
Kondappa Layout, 9th Cross:-	4	1.25	-	-	5.00	
Sathya Narayana Temple Road:-	4	3.60	-	-	14.40	
					48.90 mtrs	6241.10
				@RS.	127.63	
21/5/19 AE-02						
		Total Bill Amount RS=				18,97,552.44

CERTIFICATE:

1) Certified that the above work done is Satisfactory Completed.

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

2) Certified that the, There is no debries have been cleared to site.



Scanned by CamScanner